



Appin. No. 09/775,891
Baldwin et al.
Apparatus and Method for Repairing the Fernur
Docket Number: 82807/7115
REPLACEMENT SHEET



3/15






FIGURE 6




FIGURE 7




FIGURE 8




FIGURE 9




FIGURE 10




FIGURE II




FIGURE 12






FIGURE 13


12/15



Appin. No. 09/775,891
Baldwin et al.
Apparatus and Method for Repairing the Femur
Docket Number: 82807/7115
REPLACEMENT SHEET

13/15








FIGURE 20




FIGURE 21